Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry) UN3089 SDS: SAC011

22-Nov-2019 Ver 5 EU-EN

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)

DANGER

Flammable solids

UN3089 SDS: SAC011

22-Nov-2019 Ver 5 EU

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof electrical/
ventilating/lighting/equipment.
In case of fire: Use salt (NaCl) or class D dry powder for extinction.

Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof electrical/
ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI, 1000 Six PPG Place Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

**ATI

ATI, 1000 Six PPG Place Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry) UN3089

SDS: SAC011 22-Nov-2019 Ver 5 EU-EN

CHEMTREC: +1703-741-5970

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry) UN3089

SDS: SAC011

22-Nov-2019 Ver 5 EU

CHEMTREC: +1703-741-5970

CHEMTREC: +1703-741-5970

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection.
Keep away from heat/sparks/open flames/hot surfaces. - No smoking.
Ground/bond container and receiving equipment.
If dust clouds can occur, use explosion-proof electrical/ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment.

If dust clouds can occur, use explosion-proof electrical/ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI, 1000 Six PPG Place Pittsburgh, PA 15222 USA CHEMTREC: +1703-741-5970

*****ATI

ATI, 1000 Six PPG Place Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

Safety data sheets and labels available at ATImetals.com