Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)

UN3089 SDS: SAC011 22-Nov-2019 Ver 5 NA-EN

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATL 1000 Six PPG Place CHEMTREC: +1 800-424-9300 Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)

UN3089 SDS: SAC011 22-Nov-2019 Ver 5 NA-EN

UN3089

SDS: SAC011

22-Nov-2019 Ver 5 NA-EN

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment.

In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI, 1000 Six PPG Place CHEMTREC: +1 800-424-9300 Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment. In case of fire: Use salt (NaCl) or class D dry powder for extinction.

ATL 1000 Six PPG Place CHEMTREC: +1 800-424-9300 Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)

UN3089 SDS: SAC011 22-Nov-2019 Ver 5 NA-EN

DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment. In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI, 1000 Six PPG Place CHEMTREC: +1 800-424-9300 Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)



DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment. In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATI, 1000 Six PPG Place Pittsburgh, PA 15222 USA CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at ATImetals.com

Zirconium & Zirconium Alloy Scrap: Borings, Clippings, Shavings, Turnings and Scalpings, Fines (dry)



DANGER

Flammable solids



Wear protective gloves/protective clothing/eye protection. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. If dust clouds can occur, use explosion-proof electrical/ ventilating/lighting/equipment. In case of fire: Use salt (NaCl) or class D dry powder for extinction.



ATL 1000 Six PPG Place CHEMTREC: +1 800-424-9300 Pittsburgh, PA 15222 USA

Safety data sheets and labels available at ATImetals.com