

Hafnium Oxychloride Solution

UN1760

SDS: SAC041

20-Dec-2019 Ver 1 EU-EN

DANGER

May be corrosive to metals.
Causes severe skin burns and eye damage.
Causes serious eye damage.



Wear protective gloves/protective clothing/eye protection/face protection. Do not breathe gas/mist/vapours/spray.
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician. IF ON SKIN (or hair): Rinse cautiously with water for several minutes. Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place
Pittsburgh, PA 15222 USA

CHEMTREC: +1703-741-5970

Safety data sheets and labels available at ATImetals.com

Hafnium Oxychloride Solution

UN1760

SDS: SAC041

20-Dec-2019 Ver 1 EU-EN

DANGER

May be corrosive to metals.
Causes severe skin burns and eye damage.
Causes serious eye damage.



Wear protective gloves/protective clothing/eye protection/face protection. Do not breathe gas/mist/vapours/spray.
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician. IF ON SKIN (or hair): Rinse cautiously with water for several minutes. Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place
Pittsburgh, PA 15222 USA

CHEMTREC: +1703-741-5970

Safety data sheets and labels available at ATImetals.com

Hafnium Oxychloride Solution

UN1760

SDS: SAC041

20-Dec-2019 Ver 1 EU-EN

DANGER

May be corrosive to metals.
Causes severe skin burns and eye damage.
Causes serious eye damage.



Wear protective gloves/protective clothing/eye protection/face protection. Do not breathe gas/mist/vapours/spray.
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician. IF ON SKIN (or hair): Rinse cautiously with water for several minutes. Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place
Pittsburgh, PA 15222 USA

CHEMTREC: +1703-741-5970

Safety data sheets and labels available at ATImetals.com

Hafnium Oxychloride Solution

UN1760

SDS: SAC041

20-Dec-2019 Ver 1 EU-EN

DANGER

May be corrosive to metals.
Causes severe skin burns and eye damage.
Causes serious eye damage.



Wear protective gloves/protective clothing/eye protection/face protection. Do not breathe gas/mist/vapours/spray.
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. Immediately call a POISON CENTER or doctor/physician. IF ON SKIN (or hair): Rinse cautiously with water for several minutes. Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place
Pittsburgh, PA 15222 USA

CHEMTREC: +1703-741-5970

Safety data sheets and labels available at ATImetals.com